

Photograph 1 – NAPL Excavation Activities in Cell 13E



Photograph 2 – Backfill Activities in Cell 13E, under the Elm Street Bridge



Photograph 3 – Backfill Activities in Cell 13W



Photograph 4 - West Riverbank Retaining Wall/Backfill Activities in Cell 13W



Photograph 5 – Backfill Activities behind the West Riverbank Retaining Wall



Photograph 6 – Overview of the Temporary Dam with Slide Gates Open



Photograph 7 – Cell 13 Riverbed and Lower Riverbank Restoration/West Riverbank Retaining Wall



Photograph 8 – Removing the Temporary Dam Stop Logs during High River Flow